

CDF Operations Report

Mark Mattson (WSU)

All Experimenter's Meeting August 28, 2006


Summary: After two weeks of high efficiency, rocky this week.

Store Summary (Aug 21 - Aug 28)

Store	Start Date	Duration (hours)	CDF Initial Lum 1/(µb-s)	Delivered Lum (1/pb)	Live Lum (1/pb)	Lum w/Si (1/pb)	Comments
4915	21 Aug Mon	25.1	169.1	5.85	4.35 74.3%	3.58 61.2%	TOF HV crate, COT crate PS
4917	22 Aug Tue	30.5	183.5	7.00	5.55 79.3%	4.68 67.0%	forward muon HV, cal crate PS trip, XFT
4919	23 Aug Wed	6.2	195.4	2.89	2.24 77.7%	2.24 77.7%	cal crate PS trip
4925	25 Aug Fri	27.0	155.5	5.69	4.94 86.9%	4.79 84.1%	cen muon eXtension HV; trigger table tests
4927	26 Aug Sat	28.0	180.8	6.55	5.63 85.9%	5.63 85.9%	c-muon upgrade HV
4928	27 Aug Sun	Running	206.2				High initial deadtime, otherwise good
Total		116.7		27.98	22.71 81.2%	20.92 74.8%	

Detector Access

- Tue Morning (3 hours)
 - COT (outer tracker) readout crate PS swap
 - TOF (time-of-flight) HV control crate swap
- Wed Afternoon (1.25 hr)
- investigate silicon SE PS with drooping voltage
- Thu Morning (day shift +)
 - two silicon power supplies (SE) swapped
 - silicon cooling leak investigation
 - solenoid control software
 - dropped interlocks (sorry)
- Sat Morning (1 hr)
 - CMX (muon) wedge HV



Silicon Cooling Leak




- Definitely air leaks in East ISL (intermediate silicon layer) cooling lines
- Requires a long access (3+ days), as the work requires opening up the detector (east plug)
- Low priority problem is manageable so far

How Can CDF Improve Data Taking?

- Trigger table & high lum
 - Fri test had problems
- Increase bandwidth
 - Find bottlenecks in DAQ
- Shift efficiency



- Can we improve recovery procedures? (ex. readout crate PS trip)
- Continue progress on XFT (stereo trigger) upgrade



CDF Integrated Luminosities

